

PROJECT: Midnite Mine Remediation **REPORT NO:** 2019-013

OWNER: Newmont/Dawn Mining OPERATOR: Newmont/Dawn Mining

Summary of Work Activities or Events for this reporting period:

This weekly report provides a summary of Midnite Mine Site (Site) remediation action (RA) construction activities, quality assurance (CQA), quality control (CQC) and engineering activities for the period June 21 – June 27, 2019. The Site activities discussed in this weekly report include, but are not limited to: Site Health, Safety, and Security; Community Liaison, Project Meetings, Regulatory Oversight, Site Visitors; Site Mobilization; RA Activities; Project Documentation; and Site Inspections.

The project SharePoint site includes the Project documentation discussed in this report. Access to the project SharePoint site is available at the following link: https://amcollab.mwhtools.com/sites/midnitemine

SITE HEALTH, SAFETY, AND SECURITY

MIDNITE MINE HEALTH & SAFETY SUMMARY: Reporting Period June 21 – June 27, 2019						
FIRST AID INJURY	0	PROPERTY DAMAGE	0			
MEDICALLY TREATED INJURY	0	NEAR MISS INCIDENT	0			
RESTRICTED WORK INJURY	0	RADIATION PROTECTION PLAN (RPP) – ISSUES	0			
		REPORTED				
LOST TIME INJURY	0					

Comments: No incidents or injuries occurred during the reporting period. A mock Emergency Response Drill was conducted on June 27 with successful support and participation from Tribal EMS.

COMMUNITY LIAISON

No issues or concerns were reported or received by Newmont from the Spokane Tribe of Indians Community Liaison Officer. The Tribal Liaison Officer advised that planning is underway for a Community Meeting for the week of August 19, 2019. Mobilization notifications were provided to the Tribe during the week.

PROJECT MEETINGS, REGULATORY OVERSIGHT, AND SITE VISITORS

Weekly Progress Meeting:

The Weekly Construction Progress meeting was held at 1000 hours on Wednesday, June 26, 2019 at the on-site conference room and via conference call. Representatives from the following stakeholders attended the meeting in person or via telephone:

- EPA
- Spokane Tribe of Indians
- Jacobs
- Dawn Mining Company (DMC)/Newmont Goldcorp
- Stanted
- Ajax
- WME

Meeting Action Items:

None



EPA Plan/Document Approvals:

None

Regulatory Site Visit(s):

Steve Demus, Jacobs, representing EPA was on site June 21.

REMEDIAL WORK ACTIVITIES

Construction:

During the week of June 21 – June 27, 2019, the following activities were conducted:

- Continued excavating, hauling and placing low activity/low reactivity material from South Waste Rock Pile (SWRP) South Pond cut and the SWRP North cut in Pit 4. Material from SWRP was placed on the north, east, and west sides of Pit 4 to create the 20' rind buffer area, at the south end of the Pit 4 backfill to form the 20' radon buffer on the outer waste surface, and in the unclassified waste zone in the interior of the pit.
- Began excavating, hauling and placing high activity/high reactivity material from Ore Stockpile 1
 (Stockpile 1) in Pit 4. High activity/high reactivity material was placed in the unclassified waste
 zone in the interior of the Pit 4 backfill.
- Continued removing visible mine waste from the east Pit 4 Tie-In Area, including some material from the Pit 4 Overburden Pile. Soils from the area included some vegetative debris and were placed in the unclassified waste zone in the interior of Pit 4.
- The above materials were excavated with either excavator or loader equipment and transported and plug dumped with haul trucks. The plug dumps were leveled with a dozer into lifts not exceeding 10' thick. Table 1 presents the 2019 Pit 4 mass haul materials volume.

Table 1 - 2019 Pit 4 mass haul volume estimates

Reporting Period	Truck Loads	Estimated Volume ¹ yd ³
June 21 – June 27, 2019	3,274	91,672
2019 Cumulative	39,638	1,109,864

^{1 -} Truck load assumed to be 28 yd3

- Constructed a haul road to Stockpile 1, including burying Water Treatment Plant pipelines that cross the haul route.
- Continued work on the Infiltration Collectors (IC) on the west side of Pit 4 on the main channel and the finger drains extending to the west up the hillside.
- Wm. Winkler set up their tub grinder in the Temporary Impacted Soil Stockpile (TISS) and continued processing stockpiled timber.
- Completed monthly fence inspection and repaired fence damage and where animals had dug under the fence.
- Pit 4 tension crack was measured on June 25. The horizontal distance between movement pins remains at 53.75 inches, indicating no measurable movement.

Stormwater Pollution Prevention Plan (SWPPP)

 The Utility Crew completed SWPPP maintenance items along the West Access Road and New Access Road

Spill Prevention, Control, and Countermeasure Activities (SPCC)

None

Equipment Mobilized/Demobilized and Material Delivered

The following equipment was mobilized to the Site during this reporting period.

Wm. Winkler remobilized the wood chipper to site on June 21 following offsite repairs.



The following equipment was demobilized from the Site during this reporting period.

None

All project owned non-road diesel equipment on Site is US-EPA Tier 4 compliant. On-site rental equipment and subsequent deliveries of rental equipment may be less than Tier 4 and will be assessed at the time of delivery.

Materials:

The following material was delivered to the Site during this reporting period.

None

Dust Control and Monitoring

Six dust monitors were operated during construction activities at the locations and for the time intervals listed in Table 2. ES-4 was down from 5:30 p.m. to 2:30 a.m. during the night shift on June 21 due to a malfunctioning back-up battery.

The Total Suspended Particulate (TSP) action level of 260 micrograms/cubic meter was not exceeded during the reporting period.

Table 2 - TSP Dust Monitoring Locations during reporting period June 21 – June 27, 2019

	Location Description		Status						
Monitor ID		Start Date	Fri	Sat	ung	Mon	anı	рәм	Thu
ES-1 (stationary)	Midnite Mine Top of Pit 4	04/01/19	D/N			D/N	D/N	D/N	D/N
ES-2 (stationary)	Midnite Mine Southeast Boundary	04/01/19	D/N			D/N	D/N	D/N	D/N
ES-3 (stationary)	Midnite Mine West Boundary	04/01/19	D/N			D/N	D/N	D/N	D/N
ES-4 (roving)	Top of Stockpile 3	04/30/19	D/*			D/N	D/N	D/N	D/N
ES-5 (roving)	Spare								
ES-6 (roving)	East Side of Pit 4 next to portable light plant.	04/01/19	D/N			D/N	D/N	D/N	D/N
ES-7 (roving)	Southeast corner of Area 5	04/02/19	D/N			D/N	D/N	D/N	D/N
ES-8 (roving)	Spare								

D=Day Shift (6:00 am to 4:30 pm)

N=Night Shift (4:00 pm to 2:30 am)

E=Environmental conditions (Fog, smoke, pollen, heavy rain, etc.) - No Operation

* Equipment malfunction (Battery/Power Supply or Other)

PROJECT DOCUMENTATION

Project Submittals, Engineering Change Notices (ECNs), Requests for Information (RFIs), Non-Compliance Notifications (NCNs), CQA-CQC Field Acceptance Forms and Other Items received, changed or noted during this time-period are shown in the table below:



Table 3 – CQA Doo	cumentation							
	Project Submittals							
Submittal No.	Title	Submittal Date	CQA Acceptance Date					
02272-07.00	South Pond Geomembrane (GSE) (clarifications and additional information requested)	TBD						
02275-03.00	South Pond Geonet (GSE) (clarifications/revisions requested)	6/14/2019	TBD					
01018-34.00	2019 2 nd Quarter Progress Survey	6/21/2019	6/27/2019					
Project ECNs								
ECN No.	Title	EPA Submittal Date	EPA Response Date					
None								
Project RFIs								
RFI No.	Title	CQC Submittal Date	CQA Response Date					
2019-11	Settlement Monitoring Point – South and West Ponds	6/19/2019	6/24/2019 EPA – No Comments on 6/24/2019					
	Project NCNs							
NCN No.	Title	CQA Issue Date	CQC Response Date					
None to Date								
	CQC-CQA Field Acceptance	Forms						
CQC-CQA Acceptance No.	Title	CQC-CQA Issue Date						
2019-15	Pit 4 – West IC 2 nd Lateral/Finger Drain (Sec Acceptance	6/24/2019						
Other Items								
Item	Title	Comments						
None								

Copies of the updated CQA Logs are provided on the project SharePoint site under the 2019 CQA Folder.

SITE INSPECTIONS

Details regarding the four-phase CQA observation/inspection process for each definable work feature is summarized above within each work-feature section and are further detailed in the daily CQC/CQA reports that are available on the project SharePoint site.

Preparatory Inspections / Meetings

• None during this time-period.

Initial Phase Inspections

· None during this time-period.

Follow-up Phase and Ongoing Inspections

Daily observations/inspections by CQA during Pit 4 backfill and other construction activities for the following site-specific tasks:

- Pit 4 Backfill
 - Excavation of mine waste from the South Pond Cut/SWRP (low reactivity/low activity
 material) was used to construct the 20-foot buffer zone (rind), or was placed as general fill
 in the south bench area and in the northern portion of the pit.



- Excavation of the Overburden Pile along the east cover tie-in (low reactivity/low activity material) occurred between 6/25 and 6/26/2019 and was placed in the northern portion of the pit.
- Excavation of Stockpile 1 (high reactivity/high activity material) began on 6/26/2019 and
 was placed within the boundary of the 20-foot buffer zone in the northern portion of the pit.
- West-Side Infiltration Collection System
 - Construction of the second lateral/finger drain (4th section).

CQA accepted/observed the following:

- Subgrade (CQC-CQA Acceptance 2019-15)
- GCL placement.
- Drain gravel placement.
- Wood Chipping Activities
 - The grinder was repaired and chipping resumed on 6/24/2019.
- Construction Debris
 - o 6/21/2019 The D9 dozer crushed the failed ligno tank to a height of ≤ 2 feet and was buried in the northern portion of the pit within the Demolition Debris Zone.
 - 6/27/2019 A small amount of construction debris was buried in the north portion of the pit within the Demolition Debris Zone.
- CSWPPP Inspection
 - West Access Road
 - The main drainage area was regraded, two new sed ponds were constructed (one on each side of the road where the drainage crosses) and check dams/wattles were installed along the length of the drainage.
 - Sediment was removed from the area around the West End Road culvert and the wattles reinstalled.
 - New Access Road
 - The berm located at the east outer edge of the topsoil stockpile was repaired and the erosion along the east face was regraded.
 - Accumulated sediment was removed from all ditch runouts.
- Water bars were constructed at regular intervals along the road.

Completion Inspections

None

THREE WEEK LOOKAHEAD SCHEDULE

Three Week Lookahead Schedule

A copy of the Three Week Lookahead Schedule is provided as Attachment A.

Report completed and submitted by:

David Lee

Project Construction Director

Attachments

Attachment A – Midnite Mine 3 Week Lookahead Schedule

Photos of pertinent items are provided below.





Figure 1 – Overview of Pit 4, looking south



Figure 2 – 390 Excavators loading material from the South Pond excavation.





Figure 3 - Crushed ligno tank, looking east



Figure 4 – West Access Road main drainage following SWPPP repairs



ATTACHMENT A

MIDNITE MINE THREE WEEK LOOKAHEAD SCHEDULE



